



Figure 33. A photograph of the tripod recovered from Site 2 at the end of the second deployment. Biofouling was significantly less during the second deployment, as seen in this photograph where the surfaces of the tripod and the ADCP have minimal fouling.