



Figure 35. A photograph of the ADCP on the tripod recovered from Site 3 at the end of the second deployment. Biofouling was much less significant during this deployment. The ADCP transducers are free from any biofouling.